

Service Bulletin

10/1/97

Mazda (North America), Inc.
 1444 McGaw Ave.
 Irvine, California 92714
 Telephone (714) 261-9429



Category 3	Applicable Model/s 1986-1987 RX-7	Subject COOLANT LOSS	Bulletin No. 007/87
			Issued 6/3/87
			Revised


DESCRIPTION

To help prevent coolant loss in the 1986-1987 RX-7, Mazda has developed an air breather kit for the radiator as described in Service Bulletin Category 3, 005/87.

In order to prevent coolant loss and subsequent engine damage, you are requested to install the air breather kit on ALL RX-7 vehicles within the VIN range listed below. This work is to be performed whenever an RX-7 vehicle is brought to your service shop for scheduled or unscheduled service.

NOTE:

Check to determine if a radiator cap is installed near the sub-tank as shown below. If not, install the air breather kit. Refer to Service Bulletin Category 3, 005/87 for repair procedure and warranty information.



VIN OF PRODUCTION CHANGE

1986 RX-7 Non-Turbo:	JM1FC331 G0100001 - 199999
1987 RX-7 Non-Turbo:	JM1FC331 H0500001 - 527275
Turbo:	JM1FC332 H0130378 - 527275

IMPORTANT Service and Parts Managers should read this bulletin carefully, sign and convey all information to those concerned.

Signature _____

Service Manager

Signature _____

Parts Manager

007905