

## Sport Series ECUs - New Development # 6764: Rotary 36-1 trigger support

<b>Status:</b>	New	<b>Priority:</b>	Normal
<b>Author:</b>	Scott Hilzinger	<b>Category:</b>	
<b>Created:</b>	22/03/2011	<b>Assigned to:</b>	Nathan Clark
<b>Updated:</b>	22/03/2011	<b>Due date:</b>	
<b>Component:</b>	System		
<b>Sport Variant:</b>	All		
<b>Subject:</b>	Rotary 36-1 trigger support		
<b>Description:</b>	This is actually a standard Rotary trigger for 2 and 3 rotor MazdaSpeed engines. The Rotary community require this trigger system to be supported.		

### History

---

**22/03/2011 09:31 AM - Scott Hilzinger**

Beta tester:

Ryan J Kamm

Nuclear Criticality Safety, SB-CS

7.4614

ryank@lanl.gov