

TEXAS VEHICLE INSPECTION REPORT

Emissions and Safety Inspection

Vehicle Identification		Station Identification	
Test Date/Time:	09/16/2005.09:28	Station Name:	LUBE EXPRESS
Test Type:	Initial	Station Number:	1P28032
Test:	ASM	Station Address:	H.V. RD @ 2290 FM 40
Version Number:	0407	Station City:	HIGHLAND VILL
License Number:	748DPY	Station Zip Code:	750770000
Vehicle ID Number:	JM1FC3529L0713352	Inspector First Name:	HECTOR
Vehicle Make:	MAZD	Inspector Last Name:	BUENROSTRO
Vehicle Model:	RX7	Analyzer Number:	ES212885
Vehicle Year:	1990		
Vehicle Type:	Passenger Car	Safety Inspection Fee:	12.50
Engine Size:	1300	Safety Repair Costs:	--
Cylinders/Ignition:	R C	Emissions Test Fee:	27.00
Transmission/GVW:	Standard/3485	Emissions Repair Costs:	--
Odometer/Fuel Type:	58937/Gasoline		
		Total Inspection Cost:	39.50

Emissions Test Results

Pollutant	High Speed Emission Results (25 mph)			Low Speed Emission Results (15 mph)		
	Standard	Current Reading	Result	Standard	Current Reading	Result
HC (PPM)	168	151	PASS	173	183	FAIL
CO (%)	1.08	0.21	PASS	0.98	0.30	PASS
CO2 (%)		14.0			13.9	
O2 (%)		1.1			1.1	
NOx (ppm)	1208	313	PASS	1323	405	PASS
DILUTION (%)	>6	14.2		>6	14.2	

Gas Cap Integrity: **PASS**

Overall Result: **FAIL**

Safety Items: **PASS**

Your vehicle has failed the emissions (I/M) portion of your annual safety inspection. The rating your vehicle received indicates that the emissions related components are not