

TEXAS VEHICLE INSPECTION REPORT

Emissions and Safety Inspection

Vehicle Identification

Test Date/Time: 10/24/2006,15:48
Test Type: Initial
Test: ASM
Version Number: 0603
License Number: 748DPY
Vehicle ID Number: JM1FC3529L0713352
Vehicle Make: MAZD
Vehicle Model: RX7
Vehicle Year: 1990
Vehicle Type: Passenger Car
Engine Size: 1800
Cylinders/Ignition: 4 C
Transmission/GVW: Automatic/4452
Odometer/Fuel Type: 145442/Gasoline

Station Identification

Station Name: FAST STICKER INSPECTIONS
Station Number: IP36879
Station Address: 2290 JUSTIN RD
Station City: HIGHLAND VILL
Station Zip Code: 750770000
Inspector First Name: ARTURO
Inspector Last Name: DE LA MORA
Analyzer Number: ES213121

Safety Inspection Fee: 12.50
Safety Repair Costs: --
Emissions Test Fee: 27.00
Emissions Repair Costs: --

Total Inspection Cost: 39.50

Emissions Test Results

Pollutant	High Speed Emission Results (25 mph)			Low Speed Emission Results (15 mph)		
	Standard	Current Reading	Result	Standard	Current Reading	Result
HC(PPM)	174	24	PASS	180	29	PASS
CO (%)	1.12	0.16	PASS	1.01	0.11	PASS
CO2 (%)		14.4			14.0	
O2 (%)		0.6			1.1	
NOx(ppm)	1258	13	PASS	1378	10	PASS
DILUTION(%)	>6	14.6		>6	14.1	

Gas Cap Integrity: PASS


Safety Items: PASS

Overall Result: PASS

Certificate Number: F06770116

CONGRATULATIONS, your vehicle has passed the emissions (I/M) test portion of your safety inspection! By maintaining your vehicle in good working condition, you are doing your share for clean air. You are also saving money on gas and extending the life of your vehicle because your emissions control equipment is working as it should.

I certify that I have properly performed the emissions test according to state regulations and procedure manuals.


Certified Inspector's Signature



1748DPY



JM1FC3529L0713352



F06770116