

TEXAS VEHICLE INSPECTION REPORT
Emissions and Safety Inspection

Vehicle Identification

Test Date/Time: 04/07/2008,17:21
 Test Type: Initial
 Test: ASM
 Version Number: 0704
 License Number: 748DPY
 Vehicle ID Number: JM1FC3529L0713352
 Vehicle Make: MAZD
 Vehicle Model: RX7
 Vehicle Year/Type: 1990/Passenger Car
 Engine Size: 1300
 Cylinders/Ignition: R C
 Transmission/GVW: Automatic/3485
 Odometer/Fuel Type: 147734/Gasoline

Station Identification

Station Name: FAST STICKER INSPECTIONS
 Station/Analyzer Number: 1P36879/ES213121
 Station Address: 2290 JUSTIN RD
 Station City: HIGHLAND VILL
 Station Zip Code: 75077-0000
 Inspector First Name: ARTURO
 Inspector Last Name: DELAMORA

Safety Inspection Fee: 12.75
 Safety Repair Costs: ---
 Emissions Test Fee: 27.00
 Emissions Repair Costs: ---

 Total Inspection Cost: 39.75

Emissions Test Results

Pollutant	High Speed Emission Results (25 mph)			Low Speed Emission Results (15 mph)		
	Standard	Current Reading	Result	Standard	Current Reading	Result
HC(PPM)	168	16	PASS	173	22	PASS
CO (%)	1.08	0.05	PASS	0.98	0.07	PASS
CO2 (%)		14.4			14.3	
O2 (%)		0.5			0.6	
NOx(ppm)	1208	38	PASS	1323	37	PASS
DILUTION(%)	>6	14.5		>6	14.4	

Gas Cap Integrity: PASS

Safety Items: PASS

Overall Result: PASS

Certificate Number: M00963916

CONGRATULATIONS, your vehicle has passed the emissions (I/M) test portion of your safety inspection! By maintaining your vehicle in good working condition, you are doing your share for clean air. You are also saving money on gas and extending the life of your vehicle because your emissions control equipment is working as it should.

I certify that I have properly performed the emissions test according to state regulations and procedure manuals.

Certified Inspector's Signature



1748DPY



JM1FC3529L0713352



M00963916