

TEXAS VEHICLE INSPECTION REPORT

Emissions and Safety Inspection

Vehicle Identification

Test Date/Time: 05/16/2009,14:01
Test Type: Initial
Test: ASM
Version Number: 0801
License Number: 748DPY
Vehicle ID Number: JM1FC3529L0713352
Vehicle Make: MAZD
Vehicle Model: RX7
Vehicle Year/Type: 1990/Passenger Car
Engine Size: 1300
Cylinders/Ignition: R C
Transmission/GVW: Automatic/3485
Odometer/Fuel Type: 152151/Gasoline

Station Identification

Station Name: FAST STICKER INSPECTIONS
Station/Analyzer Number: IP36879/ES213121
Station Address: 2290 JUSTIN RD
Station City: HIGHLAND VILL.
Station Zip Code: 75077-0000
Inspector First Name: ARTURO
Inspector Last Name: DELAMORA

Safety Inspection Fee: 12.75
Safety Repair Costs: --
Emissions Test Fee: 27.00
Emissions Repair Costs: --

Total Inspection Cost: 39.75

Emissions Test Results

Pollutant	High Speed Emission Results (25 mph)			Low Speed Emission Results (15 mph)		
	Standard	RPM: 1455 Current Reading	Result	Standard	RPM: 1785 Current Reading	Result
HC(PPM)	168	75	PASS	173	27	PASS
CO (%)	1.08	0.50	PASS	0.98	0.21	PASS
CO2 (%)		14.6			14.7	
O2 (%)		0.0			0.0	
NOx(ppm)	1208	111	PASS	1323	142	PASS
DILUTION(%)	>6	15.1		>6	14.9	

Gas Cap Integrity: PASS


Overall Result: PASS

Safety Items: PASS

Certificate Number: M02391741

CONGRATULATIONS, your vehicle has passed the emissions (I/M) test portion of your safety inspection! By maintaining your vehicle in good working condition, you are doing your share for clean air. You are also saving money on gas and extending the life of your vehicle because your emissions control equipment is working as it should.

I certify that I have properly performed the emissions test according to state regulations and procedure manuals.



Certified Inspector's Signature



748DPY



JM1FC3529L0713352



M02391741