

TEXAS VEHICLE INSPECTION REPORT
Emissions and Safety Inspection

<u>Vehicle Identification</u>		<u>Station Identification</u>	
Test Date/Time:	05/08/2010,14:52	Station Name:	FAST STICKER INSPECTIONS
Test Type:	Initial	Station/Analyzer Number:	IP36879/ES213121
Test:	ASM	Station Address:	2290 JUSTIN RD
Version Number:	0906	Station City:	HIGHLAND VILL
License Number:		Station Zip Code:	75077-0000
Vehicle ID Number:	JM1FC3529L0713352	Inspector First Name:	ARTURO
Vehicle Make:	MAZD	Inspector Last Name:	DELAMORA
Vehicle Model:	RX7		
Vehicle Year/Type:	1990/Passenger Car	Safety Inspection Fee:	12.75
Engine Size:	1300	Safety Repair Costs:	--
Cylinders/Ignition:	R C	Emissions Test Fee:	27.00
Transmission/GVW:	Automatic/3485	Emissions Repair Costs:	--
Odometer/Fuel Type:	156687/Gasoline		-----
		Total Inspection Cost:	39.75

Emissions Test Results

Pollutant	High Speed Emission Results (25 mph)			Low Speed Emission Results (15 mph)		
	<u>Standard</u>	RPM: 2015		<u>Standard</u>	RPM: 1781	
		<u>Current Reading</u>	<u>Result</u>		<u>Current Reading</u>	<u>Result</u>
HC(PPM)	168	84	PASS	173	100	PASS
CO (%)	1.08	0.42	PASS	0.98	0.40	PASS
CO2 (%)		14.0			14.0	
O2 (%)		0.1			0.1	
NOx(ppm)	1208	281	PASS	1323	198	PASS
DILUTION(%)	>6	14.4		>6	14.4	

Gas Cap Integrity: PASS

Overall Result: PASS

Safety Items: PASS

Certificate Number: M03003512

CONGRATULATIONS, your vehicle has passed the emissions (I/M) test portion of your safety inspection! By maintaining your vehicle in good working condition, you are doing your share for clean air. You are also saving money on gas and extending the life of your vehicle because your emissions control equipment is working as it should.

I certify that I have properly performed the emissions test according to state regulations and procedure manuals.

