

TEXAS VEHICLE INSPECTION REPORT
Emissions and Safety Inspection

Vehicle Identification		Station Identification	
Test Date/Time:	09/19/2005,15:40	Station Name:	LUBE EXPRESS
Test Type:	Reinspection	Station Number:	1P28032
Test:	ASM	Station Address:	H.V. RD @ 2290 FM 40
Version Number:	0407	Station City:	HIGHLAND VILL
License Number:	748DPY	Station Zip Code:	750770000
Vehicle ID Number:	JM1FC3529L0713352	Inspector First Name:	HECTOR
Vehicle Make:	MAZD	Inspector Last Name:	BUENROSTRO
Vehicle Model:	RX7	Analyzer Number:	ES212885
Vehicle Year:	1990	Safety Inspection Fee:	---
Vehicle Type:	Passenger Car	Safety Repair Costs:	---
Engine Size:	1300	Emissions Test Fee:	---
Cylinders/Ignition:	R C	Emissions Repair Costs:	---
Transmission/GVW:	Standard/3485		-----
Odometer/Fuel Type:	58976/Gasoline	Total Inspection Cost:	---

Emissions Test Results

Pollutant	High Speed Emission Results (25 mph)			Low Speed Emission Results (15 mph)		
	Standard	RPM: 2010 Current Reading	Result	Standard	RPM: 1774 Current Reading	Result
HC(PPM)	168	37	PASS	173	59	PASS
CO (%)	1.08	0.03	PASS	0.98	0.03	PASS
CO2 (%)		13.7			13.5	
O2 (%)		0.9			1.2	
NOx(ppm)	1208	21	PASS	1323	32	PASS
DILUTION(%)	>6	13.7		>6	13.5	

Gas Cap Integrity: PASS

Overall Result: PASS

Safety Items: PASS

Certificate Number: F06128201