

TEXAS VEHICLE INSPECTION REPORT

Emissions and Safety Inspection

Vehicle Identification

Test Date/Time: 05/31/2011,16:44
Test Type: Initial
Test: ASM
Version Number: 1101
License Number: 748DPY
Vehicle ID Number: JM1FC3529L0713352
Vehicle Make: MAZD
Vehicle Model: RX7
Vehicle Year/Type: 1990/Passenger Car
Engine Size: 1300
Cylinders/Ignition: R C
Transmission/GVW: Automatic/3485
Odometer/Fuel Type: 161797/Gasoline

Station Identification

Station Name: FAST STICKER INSPECTIONS
Station/Analyzer Number: 1P36879/ES213121
Station Address: 2290 JUSTIN RD
Station City: HIGHLAND VILL
Station Zip Code: 75077-0000
Inspector First Name: ARTURO
Inspector Last Name: DELAMORA

Safety Inspection Fee: 12.75
Safety Repair Costs: --
Emissions Test Fee: 27.00
Emissions Repair Costs: --

Total Inspection Cost: 39.75

Emissions Test Results

Pollutant	High Speed Emission Results (25 mph)			Low Speed Emission Results (15 mph)		
	Standard	Current Reading	Result	Standard	Current Reading	Result
HC(PPM)	168	160	PASS	173	173	PASS
CO (%)	1.08	0.55	PASS	0.98	0.53	PASS
CO2 (%)		13.7			13.7	
O2 (%)		0.3			0.3	
NOx(ppm)	1208	359	PASS	1323	375	PASS
DILUTION(%)	>6	14.3		>6	14.2	

Gas Cap Integrity: PASS

Overall Result: PASS

Safety Items: PASS

Certificate Number: F00134183

CONGRATULATIONS, your vehicle has passed the emissions (I/M) test portion of your safety inspection! By maintaining your vehicle in good working condition, you are doing your share for clean air. You are also saving money on gas and extending the life of your vehicle because your emissions control equipment is working as it should.

I certify that I have properly performed the emissions test according to state regulations and procedure manuals

Certified Inspector's Signature



1748DPY



JM1FC3529L0713352



F00134183