



www.esp-global.com

Smog Check Vehicle Inspection Report (VIR)

Vehicle Information

www.autorepa...

Test Date/Time: 04/14/2018@10:12:48

Model Year:	1987	Make:	MAZDA	Model:	RX7
License:	[REDACTED]	State:	CA	VIN:	[REDACTED]
Engine Size:	1.30 L	Type:	Passenger Car	Transmission:	Manual
GVWR:	N/A	Test Weight:	3000 - w/ me in car	Cylinders:	Rotary
Odometer:	157,384	Certification:	California	VLT Record #:	[REDACTED]
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	Change of Ownership

Overall Test Results

Comprehensive Visual Inspection: **Pass** Functional Check: **Pass** Emissions Test: **Gross Polluter**

Failed

Repairing your vehicle is necessary to help California reduce smog-forming emissions and reach our air quality goals.

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	Not applicable	OBD System Checks
Pass	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Not applicable	EGR Functional	Pass	Ignition Timing: PA05	Pass	Other Emission Related Components
Pass	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Pass	Fuel Evaporative Controls Functional		

ASM Emission Test Results

Test	RPM	%CO2		HC (PPM)			CO (%)			NO (PPM)			Results
		MEAS	MEAS	MAX	GP	MEAS	MAX	GP	MEAS	MAX	AVE	GP	
15 mph	1795	12.7	0.0	85	296	648	0.54	2.26	3.49	565	2014	117	GROSS POLLUTER
25 mph	2870	12.0	0.0	67	246	491	0.45	2.15	4.53	522	1814	89	GROSS POLLUTER

MAX = Maximum Allowable Emissions

GP = Gross Polluter Limits

MEAS = Amount Measured

Failed smog check? Financial assistance may be available. To get an application, visit the Bureau of Automotive Repair's website at www.smogcheck.ca.gov or call toll-free at 800.952.5210.

Si usted ha fallado el examen de smog, asistencia financiera puede estar disponible. Para obtener una solicitud, visite www.smogcheck.ca.gov o llámenos a BAR al 800.952.5210.

Smog Check Inspection Station Information

ALL CAR LLC
 940 Dell Ave Campbell CA 95008
 14088712275
 Station Number: RC273402

Technician Name/Number: SINGH, KALWINDAR/EO136444
 Repair Tech Name/Number:
 Software Version/EIS Number: 1803 / EP728424

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

Date: 4/14/18

Technician's Signature: [Signature]

