



OREGON DEPARTMENT ON ENVIRONMENTAL QUALITY

VEHICLE INSPECTION PROGRAM

Overall Result - Fail

Station Information

DATE: 8/11/2006 12:40:44 PM

STATION: 06

LANE: 1

INSPECTOR: Jzertan

UNIT: OR060102

Vehicle Information

VIN:	[REDACTED]	Cylinders:	99	Fuel System:	Either
Plate:	RACRDY	Body Type:	1	Fuel:	G
Vehicle Year:	1993	Transmission:	M	Odometer:	80 X 1000
Vehicle Make:	MAZDA	Displacement:	1.3	Weight Class:	0 to 6000 lbs
Vehicle Model:	RX7	Class:	P	Catalyst:	Yes

TAILPIPE EMISSION TEST RESULTS - Fail

Readings:	HC STD	CO STD	Dilution	HC	CO	CO2	RPM
Idle Results:	220	1	6	914	3.9296	12.5	1200
2500 Results:	220	1	6	359	4.5073	12.1	2450
2nd Idle:	220	1	6	NA	NA	NA	1200
Dual Fuel: (If Applicable)							
Idle Results:	220	1	6	NA	NA	NA	NA
2500 Results:	220	1	6	NA	NA	NA	NA
2nd Idle:	220	1	6	NA	NA	NA	NA

Smoke Test: Pass

Noise Test: Pass Exhaust 1: N/A Exhaust 2: N/A Standard: N/A

Fuel Cap: Pass

Catalytic Converter: Pass

(OTE: Inspectors are prohibited from offering diagnostic information related to the vehicle readings or from making any estimates or recommendations regarding repairs or repair facilities. A vehicle with an inaccessible exhaust system will be rejected from the test area.