

Smog Check Vehicle Inspection Report (VIR)



www.autorepair.ca.gov

Vehicle Information

Model Year: 1993 Make: MAZDA Model: RX7
 License: NONE State: XX VIN: JM1FD3310P0205199
 Engine Size: 1.30 L Type: Passenger Car Transmission: Manual
 GVWR: N/A Test Weight: 3125 Cylinders: Rotary
 Odometer: 27,598 Certification: Federal VLT Record #: 24921
 Fuel Type: Gasoline Exhaust: Single Inspection Reason: Initial Registration

Overall Test Results

Comprehensive Visual Inspection: **Pass** Functional Check: **Pass** Emissions Test: **Fail**

Repairing your vehicle is necessary to help California reduce smog-forming emissions and reach our air quality goals

Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of crankcase and cold start emissions which are not measured during the ASM test)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	Pass	OBD System Checks
Pass	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb / Fuel Injection
Not applicable	EGR Functional	Non Adjustable	Ignition Timing: N 00	Pass	Other Emission Related Components
Pass	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Fuel Cap Visual	Not applicable	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Not applicable	Fuel Evaporative Controls Functional		

ASM Emission Test Results

Test	RPM	%CO2		HC (PPM)			CO (%)			NO (PPM)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
15 mph	2423	13.3	2.5	61	27	24	0.36	0.09	0.03	493	157	259	Pass
25 mph	2760	13.5	2.0	37	18	16	0.35	0.09	0.00	516	161	542	Fail

MAX = Maximum Allowable Emissions AVE = Average Emissions For Passing Vehicles MEAS = Amount Measured

No match has been found or test has been performed off-line. The consumer is responsible for retaining the VIR for reference throughout the vehicle registration process. Failed smog check? Financial assistance may be available. To get an application, visit the Bureau of Automotive Repair's website at www.smogcheck.ca.gov or call toll-free at 800.952.5210.

Si usted ha fallado el examen de smog, asistencia financiera puede estar disponible. Para obtener una solicitud, visite www.smogcheck.ca.gov o llámenos a BAR al 800.952.5210.

Smog Check Inspection Station Information

SMOG CHECK Technician Name/Number: MCGLYNN, TRACY/EO135091
 3921 Soquel Drive Soquel, CA 95073 Repair Tech Name/Number:
 831-462-0355 Software Version/EIS Number: 1904 / EP728752
 Station Number: RC270585

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

Date: 10/29/19 Technician's Signature: [Signature]