



www.esp-global.com

# Smog Check Vehicle Inspection Report (VIR)



www.autorepair.ca.gov

## Vehicle Information

Test Date/Time: 11/07/2019@14:08:03

Model Year:	1993	Make:	MAZDA	Model:	RX7
License:	NONE	State:	XX	VIN:	JM1FD3310P0205199
Engine Size:	1.30 L	Type:	Passenger Car	Transmission:	Manual
GVWR:	N/A	Test Weight:	N/A	Cylinders:	Rotary
Odometer:	27,729	Certification:	Federal	VLT Record #:	24921
Fuel Type:	Gasoline	Exhaust:	Single	Inspection Reason:	Initial Registration

## Overall Test Results

**Congratulations! Your vehicle passed the enhanced Smog Check inspection, which helps California reach its daily goal of removing an extra 100 tons of smog-forming emissions from the air. Thank you for keeping your vehicle well maintained.**

**Smog Check Certificate Number: RA305601**

**DMV ID Number: 9894A116R809**

Your Smog Check certificate has been electronically transmitted to DMV.  
Your certificate is valid for 90 days from date of issuance.  
Please keep this copy for your records.

## Emission Control Systems Visual Inspection/Functional Check Results

(Visual/Functional tests are used to assist in the identification of oxides of nitrogen, crankcase and cold start emissions which are not measured during the Idle test.)

Result	ECS	Result	ECS	Result	ECS
Pass	PCV	Not applicable	Thermostatic Air Cleaner	Pass	Fuel Evaporative Controls
Pass	Catalytic Converter	Pass	Air Injection	Pass	OBD System Checks
Pass	EGR Visual	Pass	Vacuum Lines to Sensors / Switches	Pass	Carb. / Fuel Injection
Pass	EGR Functional	Non Adjustable	Ignition Timing: N 00	Pass	Other Emission Related Components
Pass	Fuel Cap Functional	Pass	Wiring to Sensors	Pass	Oxygen Sensor
Pass	Fuel Cap Visual	Pass	Fillpipe Restrictor	Pass	Liquid Fuel Leaks
Pass	Spark Controls	Pass	Fuel Evaporative Controls Functional		

## Idle Emission Test Results

Test	RPM	%CO2		HC (PPM)			CO (%)			Results
		MEAS	MEAS	MAX	AVE	MEAS	MAX	AVE	MEAS	
Idle	723	10.9	6.0	100	17	3	1.00	0.00	0.00	Pass
2500 RPM	2564	9.2	8.0	130	12	5	1.00	0.10	0.00	Pass

MAX = Maximum Allowable Emissions

AVE = Average Emissions For Passing Vehicles

MEAS = Amount Measured

## Smog Check Inspection Station Information

SANTA CRUZ MOTORSPORTS  
211 CEDAR STREET, SANTA CRUZ, CA 95060  
(831)-458-1155  
Station Number: RC244863

Technician Name/Number: NIEBLAS, DANIEL/EO640294  
Repair Tech Name/Number:  
Software Version/EIS Number: 1805 / EP831190

I certify, under penalty of perjury, under the laws of the State of California, that I performed the inspection in accordance with all bureau requirements, and that the information listed on this vehicle inspection report is true and accurate.

11/7/19  
Date

*Daniel Nieblas*  
Technician's Signature