



9675 Southwest FWY
Houston, TX 77074

Phone: 281-738-3635

Customer: Peter Morel
Address:


Phone 1: (410) 920-3430
Phone 2:

Date: 1/5/2021

Injector p/n n/a	Year		Make		Model		Engine	
	1	2	3	4	5	6	7	8
Resistance in Ohm	12.1	12.1	8.5	8.5				
Inductance	Pass	Pass	Pass	Pass				
Leak Test Fail/Pass	Pass	Pass	Pass	Pass				
	Pass	Pass	Pass	Pass				
Spray Pattern Good/Fair/Poor	Fair	Fair	Fair	Fair				
	Good	Good	Good	Good				
Static Flow Before	852	816	1980	2040				
Static Flow After	876	876	2100	2100				

Flow In LB/HR	83.31	83.31	199.71	199.71				
% Change per Injector	2.82	7.35	6.06	2.94				

Test Pressure (PSI) **43.2**



Notes:

Thank you for your business. If you are pleased with our service, please tell others about us.